

C.O.C.: DW29615

REPORT No. B12-19802

**Report To:**

**Property Management Inc**  
 48 King Street,  
 Trenton Ont K8V 3V8 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 07-Aug-12

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 13-Aug-12

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

<b>Client I.D.</b>	Trailer #24	Pumphouse #1		
<b>Sample I.D.</b>	B12-19802-1	B12-19802-2		
<b>Date Collected</b>	07-Aug-12	07-Aug-12		

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	08-Aug-12/K	0			
E coli	cfu/100mL	1	MOE E3407	08-Aug-12/K	0			
Nitrite (N)	mg/L	0.1	SM4110C	08-Aug-12/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	08-Aug-12/O		< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	08-Aug-12/O		< 0.1		



Michelle Dubien  
 Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.