

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW38584

REPORT No. B12-23305

Report To:	Caduceon Environmental Laboratories		
Property Management Inc	285 Dalton Ave		
48 King Street,	Kingston Ontario K7K 6Z1		
Trenton Ont K8V 3V8 Canada	Tel: 613-544-2001		
Attention: Isaac Berman	Fax: 613-544-2770		
DATE RECEIVED: 12-Sep-12	JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse		
DATE REPORTED: 17-Sep-12	P.O. NUMBER:		
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260019591		

	Parameter Units M.D.L. Reference Method Date Analyzed/Site		Total	E coli		
			Coliform cfu/100mL	cfu/100mL		
			1		 	
			MOE E3407	MOE E3407		
			13-Sep-12/K	13-Sep-12/K		
Client I.D.	Sample I.D.	Date Collected				
Trailer #24	B12-23305-1	12-Sep-12	0	0		

R. Jeco po

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.