

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW38587

REPORT No. B12-23577

Report To:	Caduceon Environmental Laboratories		
Property Management Inc	285 Dalton Ave		
48 King Street,	Kingston Ontario K7K 6Z1		
Trenton Ont K8V 3V8 Canada	Tel: 613-544-2001		
Attention: Isaac Berman	Fax: 613-544-2770		
DATE RECEIVED: 17-Sep-12	JOB/PROJECT NO.: HMR Estates Pump House		
DATE REPORTED: 19-Sep-12	P.O. NUMBER:		
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768		

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units M.D.L. Reference Method		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
	Date Analyzed/Site		17-Sep-12/K	17-Sep-12/K	17-Sep-12/K	
Client I.D.	Sample I.D.	Date Collected			-	
19A Buffalo Dr	B12-23577-1	17-Sep-12	0	0	< 10	
Pupmhouse Raw	B12-23577-2	17-Sep-12	0	0		

R. Jeco po

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Richard Lecompte Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.