

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW38588

REPORT No. B12-23573

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
48 King Street,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 3V8 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 17-Sep-12	JOB/PROJECT NO .: Lyn Valley Mobile Home			
DATE REPORTED: 19-Sep-12	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465			

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units		cfu/100mL	cfu/100mL	cfu/mL	
	M.D.L.		1	1	10	
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			17-Sep-12/K	17-Sep-12/K	17-Sep-12/K	
Client I.D.	Sample I.D.	Date Collected		-	-	-
70 Main St W Lyn	B12-23573-1	17-Sep-12	0	0	< 10	
Pumphouse Raw	B12-23573-2	17-Sep-12	0	0		

R. Jeco po

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Richard Lecompte Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.