

C.O.C.: DW47844

REPORT No. B12-32163

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 20-Dec-12

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 24-Dec-12

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Client I.D.	Trailer #24			
Sample I.D.	B12-32163-1			
Date Collected	20-Dec-12			

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	20-Dec-12/K	0			
E coli	cfu/100mL	1	MOE E3407	20-Dec-12/K	0			



Michelle Dubien
 Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.