

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW47980 REPORT No. B13-02400

Report To:

**Property Management Inc** 

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 31-Jan-13

DATE REPORTED: 04-Feb-13

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter Units M.D.L. Reference Method		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L.			1	10	
	Reference Meth			MOE E3407	SM9215D	
	Date Analyzed/Site		31-Jan-13/K	31-Jan-13/K	31-Jan-13/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr.	B13-02400-1	31-Jan-13	0	0	< 10	

R. Lea Bo

Richard Lecompte Supervisor/Microbiology