

**C.O.C.: DW29819**

**REPORT No. B13-03476**

**Report To:**

**Property Management Inc**  
 48 King Street,  
 Trenton Ont K8V 3V8 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 13-Feb-13

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 19-Feb-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

<b>Client I.D.</b>	19A Buffalo Dr.	Pumphouse	19A Buffalo Dr.	
<b>Sample I.D.</b>	B13-03476-1	B13-03476-2	B13-03476-3	
<b>Date Collected</b>	13-Feb-13	13-Feb-13	13-Feb-13	

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	13-Feb-13/K	0			
E coli	cfu/100mL	1	MOE E3407	13-Feb-13/K	0			
Heterotrophic Plate Count	cfu/mL	10	SM9215D	13-Feb-13/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		
Chloroform	µg/L	0.3	EPA 8260	14-Feb-13/O			1.1	
Bromodichloromethane	µg/L	0.1	EPA 8260	14-Feb-13/O			< 0.1	
Dibromochloromethane	µg/L	0.1	EPA 8260	14-Feb-13/O			< 0.1	
Bromoform	µg/L	0.1	EPA 8260	14-Feb-13/O			< 0.1	
Total Trihalomethanes	µg/L	0.3	EPA 8260	14-Feb-13/O			1.1	



Michelle Dubien  
 Lab Manager

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.