

C.O.C.: DW2924

REPORT No. B13-03478

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 13-Feb-13

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 15-Feb-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed	Client I.D.			
					Trailer #24	Pumphouse		
Total Coliform	cfu/100mL	1	MOE E3407	13-Feb-13/K	0			
E coli	cfu/100mL	1	MOE E3407	13-Feb-13/K	0			
Nitrite (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	14-Feb-13/O		< 0.1		



Michelle Dubien
 Lab Manager

M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.