

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW50887 REPORT No. B13-10219

Report To:

Property Management Inc

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 06-May-13

DATE REPORTED: 10-May-13

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter Units M.D.L. Reference Method Date Analyzed/Site		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			07-May-13/K	07-May-13/K	07-May-13/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St W	B13-10219-1	06-May-13	0	0	< 10	
Pumphouse-Raw	B13-10219-2	06-May-13	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor