

C.O.C.: DW50022

REPORT No. B13-11386

Report To:

Property Management Inc
48 King Street,
Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 15-May-13

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 22-May-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

			Client I.D.	70 Main St. W	Pumphouse		
			Sample I.D.	B13-11386-1	B13-11386-2		
			Date Collected	15-May-13	15-May-13		
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed			
Nitrite (N)	mg/L	0.1	SM4110C	16-May-13/O		< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	16-May-13/O		< 0.1	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	16-May-13/O		< 0.1	
Chloroform	µg/L	0.3	EPA 8260	16-May-13/O	< 0.3		
Bromodichloromethane	µg/L	0.1	EPA 8260	16-May-13/O	< 0.1		
Dibromochloromethane	µg/L	0.1	EPA 8260	16-May-13/O	< 0.1		
Bromoform	µg/L	0.1	EPA 8260	16-May-13/O	< 0.1		
Total Trihalomethanes	µg/L	0.3	EPA 8260	16-May-13/O	< 0.3		



Richard Lecompte
Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.