

Client committed. Quality assured.

## CERTIFICATE OF ANALYSIS

Final Report-Microbiology

## C.O.C.: DW53748

## **REPORT No. B13-13640**

Report To:	Caduceon Environmental Laboratories		
operty Management Inc 285 Dalton Ave			
48 King Street,	Kingston Ontario K7K 6Z1		
Trenton Ont K8V 3V8 Canada Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770		
DATE RECEIVED: 05-Jun-13	JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse		
DATE REPORTED: 10-Jun-13	P.O. NUMBER:		
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260019591		

	Parameter		Total Coliform	E coli		
	Units		cfu/100mL	cfu/100mL		
	M.D.L.		1	1		
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407		
			06-Jun-13/K	06-Jun-13/K		
Client I.D.	Sample I.D.	Date Collected				
Trailer #24	B13-13640-1	05-Jun-13	0	0		
Pumphouse Raw	B13-13640-2	05-Jun-13	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.