

C.O.C.: DW49284

REPORT No. B13-20172

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 06-Aug-13

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 13-Aug-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed	Client I.D.	70 Main St.W	70 Main St.W	Pumphouse
					Sample I.D.	06-Aug-13	06-Aug-13	06-Aug-13
Date Collected					06-Aug-13	06-Aug-13	06-Aug-13	
Total Coliform	cfu/100mL	1	MOE E3407	06-Aug-13/K	0			
E coli	cfu/100mL	1	MOE E3407	06-Aug-13/K	0			
Heterotrophic Plate Count	cfu/mL	10	SM9215D	06-Aug-13/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	07-Aug-13/O				< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	07-Aug-13/O				< 0.1
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	07-Aug-13/O				< 0.1
Chloroform	µg/L	0.3	EPA 8260	07-Aug-13/O			0.7	
Bromodichloromethane	µg/L	0.1	EPA 8260	07-Aug-13/O			1.9	
Dibromochloromethane	µg/L	0.1	EPA 8260	07-Aug-13/O			7.1	
Bromoform	µg/L	0.1	EPA 8260	07-Aug-13/O			8.0	
Total Trihalomethanes	µg/L	0.3	EPA 8260	07-Aug-13/O			17.7	



Richard Lecompte
 Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.