

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW54221 REPORT No. B13-24404

Report To:

Property Management Inc

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 17-Sep-13

DATE REPORTED: 19-Sep-13

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter		E coli	Heterotrophic Plate Count	
	Units M.D.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			17-Sep-13/K	17-Sep-13/K	17-Sep-13/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B13-24404-1	17-Sep-13	0	0	< 10	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie

for Richard Lecompte Lab Supervisor