

C.O.C.: DW54767

REPORT No. B13-28673

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 31-Oct-13

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 01-Nov-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

| | | | | | |
|---------------------------|----------------|-------------|--|--|--|
| Parameter | Total Coliform | E coli | | | |
| Units | cfu/100mL | cfu/100mL | | | |
| M.D.L. | 1 | 1 | | | |
| Reference Method | MOE E3407 | MOE E3407 | | | |
| Date Analyzed/Site | 31-Oct-13/K | 31-Oct-13/K | | | |

| | | | | | | |
|--------------------|--------------------|-----------------------|---|---|--|--|
| Client I.D. | Sample I.D. | Date Collected | | | | |
| Trailer #24 | B13-28673-1 | 31-Oct-13 | 0 | 0 | | |



Natasha Popkie

for Richard Lecompte Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.