

C.O.C.: G33884

REPORT No. B13-28984

Report To:

Property Management Inc
48 King Street,
Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 05-Nov-13

JOB/PROJECT NO.:

DATE REPORTED: 20-Nov-13

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

			Client I.D.		Lyn Valley Mobile Park- Effluent			
			Sample I.D.		B13-28984-1			
			Date Collected		05-Nov-13			
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
E coli	cfu/100mL	1	SM9222B	05-Nov-13/K	8000			
pH @25°C	pH Units		SM4500H+	06-Nov-13/K	7.83			
CBOD5	mg/L	2	SM 5210B	06-Nov-13/K	< 2			
Total Suspended Solids	mg/L	2	SM2540D	05-Nov-13/K	3			
Phosphorus-Total	mg/L	0.01	E3199A.1	18-Nov-13/K	0.32			
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	18-Nov-13/K	0.8			
Ammonia (N)-Total	mg/L	0.005	SM4500-NH3-H	15-Nov-13/K	0.454			
Ammonia (N)-unionized	mg/L	0.005	CALC	15-Nov-13/K	0.011			
Nitrite (N)	mg/L	0.1	SM4110C	06-Nov-13/O	0.2			
Nitrate (N)	mg/L	0.1	SM4110C	06-Nov-13/O	1.1			



Michelle Dubien
Lab Manager

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.