

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW54969 REPORT No. B13-31370

Report To:

**Property Management Inc** 

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 03-Dec-13

DATE REPORTED: 04-Dec-13

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

P.O. NUMBER:

WATERWORKS NO. 260019591

	Units M.D.L. Reference Method Date Analyzed/Site		Total Coliform cfu/100mL	E coli cfu/100mL		
			1	1		
			MOE E3407	MOE E3407		
			03-Dec-13/K	03-Dec-13/K		
Client I.D.	Sample I.D.	Date Collected				
Trailer #24	B13-31370-1	03-Dec-13	0	0		
Pumphouse Raw	B13-31370-2	03-Dec-13	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie

for Richard Lecompte Lab Supervisor