

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW52372 REPORT No. B14-01418

Report To:

Property Management Inc

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 21-Jan-14

DATE REPORTED: 23-Jan-14

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units M.D.L.		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L.			1	10	
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			21-Jan-14/K	21-Jan-14/K	21-Jan-14/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St. W	B14-01418-1	21-Jan-14	0	0	10	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie

for Richard Lecompte Lab Supervisor