

C.O.C.: DW52252

REPORT No. B14-02338

Report To:

Property Management Inc
48 King Street,
Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 04-Feb-14

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 10-Feb-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

			Client I.D.	#24	Pumphouse	Pumphouse	
			Sample I.D.	B14-02338-1	B14-02338-2	B14-02338-3	
			Date Collected	04-Feb-14	04-Feb-14	04-Feb-14	
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	04-Feb-14/K	0	0	
E coli	cfu/100mL	1	MOE E3407	04-Feb-14/K	0	0	
Nitrite (N)	mg/L	0.1	SM4110C	06-Feb-14/O			< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	06-Feb-14/O			5.0
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	06-Feb-14/O			5.0



M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.