

ENVIRONMENTAL LABORATOR ES Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW52257

REPORT No. B14-04315

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
48 King Street,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 3V8 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 04-Mar-14	JOB/PROJECT NO.: HMR Estates Pump House			
DATE REPORTED: 06-Mar-14	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768			

	Parameter Units		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
	M.D.L.		1	1	10	
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			04-Mar-14/K	04-Mar-14/K	04-Mar-14/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B14-04315-1	04-Mar-14	0	0	< 10	
Pumphouse-Raw	B14-04315-2	04-Mar-14	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.