

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW59276 REPORT No. B14-13228

Report To:

Property Management Inc

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 09-Jun-14

DATE REPORTED: 11-Jun-14

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter Units M.D.L. Reference Method Date Analyzed/Site		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			09-Jun-14/K	09-Jun-14/K	09-Jun-14/K	
Client I.D.	Sample I.D.	Date Collected				·
19A Buffalo Dr	B14-13228-1	09-Jun-14	0	0	< 10	
Pumphouse-Raw	B14-13228-2	09-Jun-14	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie

for Richard Lecompte Lab Supervisor