

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW54988 REPORT No. B14-15059

Report To:

Property Management Inc

48 King Street,

Trenton Ont K8V 3V8 Canada **Attention:** Isaac Berman

DATE RECEIVED: 24-Jun-14

DATE REPORTED: 27-Jun-14

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units M.D.L. Reference Method		E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
	Units					
	M.D.L.					
	Reference Meth					
	Date Analyzed/Site		24-Jun-14/K	24-Jun-14/K	24-Jun-14/K	
Client I.D.	Sample I.D.	Date Collected				•
70 Main St. W	B14-15059-1	24-Jun-14	0	0	< 10	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie

for Richard Lecompte Lab Supervisor