

C.O.C.: DW59684

REPORT No. B14-15960

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 02-Jul-14

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 03-Jul-14

P.O. NUMBER:


SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

| Parameter | | | Total Coliform | E coli | | | |
|--------------------|-------------|----------------|----------------|-------------|--|--|--|
| Units | | | cfu/100mL | cfu/100mL | | | |
| M.D.L. | | | 1 | 1 | | | |
| Reference Method | | | MOE E3407 | MOE E3407 | | | |
| Date Analyzed/Site | | | 02-Jul-14/K | 02-Jul-14/K | | | |
| Client I.D. | Sample I.D. | Date Collected | | | | | |
| #24 | B14-15960-1 | 02-Jul-14 | 0 | 0 | | | |

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill


 Natasha Popkie
 for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.