

C.O.C.: DW58422

REPORT No. B14-19350

Report To:

Property Management Inc
 48 King Street,
 Trenton Ont K8V 3V8 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 05-Aug-14

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 12-Aug-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19 A Buffalo Dr.	Pumphouse Raw	19 A Buffalo Dr	Pumphouse
Sample I.D.	B14-19350-1	B14-19350-2	B14-19350-3	B14-19350-4
Date Collected	04-Aug-14	04-Aug-14	04-Aug-14	04-Aug-14

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	05-Aug-14/K	0	0		
E coli	cfu/100mL	1	MOE E3407	05-Aug-14/K	0	0		
Heterotrophic Plate Count	cfu/mL	10	SM9215D	05-Aug-14/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-14/O				< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	05-Aug-14/O				< 0.1
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-14/O				< 0.1
Chloroform	µg/L	0.3	EPA 8260	06-Aug-14/O			0.7	
Bromodichloromethane	µg/L	0.1	EPA 8260	06-Aug-14/O			0.4	
Dibromochloromethane	µg/L	0.1	EPA 8260	06-Aug-14/O			0.3	
Bromoform	µg/L	0.1	EPA 8260	06-Aug-14/O			< 0.1	
Total Trihalomethanes	µg/L	0.3	EPA 8260	06-Aug-14/O			1.5	



Richard Lecompte
 Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.