

C.O.C.: DW58421

REPORT No. B14-19351

**Report To:**

**Property Management Inc**  
 48 King Street,  
 Trenton Ont K8V 3V8 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

DATE RECEIVED: 05-Aug-14

JOB/PROJECT NO.: 104 Ellisville Rd - Pumpouse

DATE REPORTED: 07-Aug-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

			Client I.D.	#24	Pumpouse	Pumpouse	
			Sample I.D.	B14-19351-1	B14-19351-2	B14-19351-3	
			Date Collected	04-Aug-14	04-Aug-14	04-Aug-14	
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	05-Aug-14/K	0	1	
E coli	cfu/100mL	1	MOE E3407	05-Aug-14/K	0	0	
Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-14/O			< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	05-Aug-14/O			4.8
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-14/O			4.8



Richard Lecompte  
 Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.