

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW59831

REPORT No. B14-26539

Report To: Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave		
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1		
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001		
Attention: Isaac Berman	Fax: 613-544-2770		
DATE RECEIVED: 14-Oct-14	JOB/PROJECT NO .: Lyn Valley Mobile Home		
DATE REPORTED: 17-Oct-14	P.O. NUMBER:		
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465		

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units		cfu/100mL	cfu/100mL	cfu/mL	
	M.D.L.		1	1	10	
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			14-Oct-14/K	14-Oct-14/K	14-Oct-14/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St W	B14-26539-1	13-Oct-14	0	0	10	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.