

C.O.C.: T0077

REPORT No. B14-28118

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 29-Oct-14

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 31-Oct-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Parameter	Total Coliform	E coli	Heterotrophic Plate Count		
Units	cfu/100mL	cfu/100mL	cfu/mL		
M.D.L.	1	1	10		
Reference Method	MOE E3407	MOE E3407	SM9215D		
Date Analyzed/Site	29-Oct-14/K	29-Oct-14/K	29-Oct-14/K		

Client I.D.	Sample I.D.	Date Collected				
#24	B14-28118-1	29-Oct-14	0	0	< 10	



Natasha Popkie
 for Richard Lecompte Lab Supervisor

M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill