

C.O.C.: G44705

REPORT No. B14-28666

Report To:

Property Management Inc
323 Dundas Street East, Unit 3,
Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 04-Nov-14

JOB/PROJECT NO.: Lyn Valley Mobile Park

DATE REPORTED: 17-Nov-14

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

			Client I.D.		Lyn Valley-Effluent	Lyn Valley-Raw		
			Sample I.D.		B14-28666-1	B14-28666-2		
			Date Collected		04-Nov-14	04-Nov-14		
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
E coli	cfu/100mL	1	SM9222B	04-Nov-14/K	500	350000		
pH @25°C	pH Units		SM4500H+	06-Nov-14/K	8.08	7.36		
CBOD5	mg/L	2	SM 5210B	05-Nov-14/K	< 2	132		
Total Suspended Solids	mg/L	3	SM2540D	04-Nov-14/K	5	60		
Phosphorus-Total	mg/L	0.01	E3199A.1	05-Nov-14/K	3.48	7.15		
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	07-Nov-14/K	5.15	50.8		
Ammonia (N)-unionized	mg/L	0.01	CALC	07-Nov-14/K	0.25	0.49		
Nitrite (N)	mg/L	0.1	SM4110C	10-Nov-14/O	1.3	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	10-Nov-14/O	7.3	< 0.1		



M.D.L. = Method Detection Limit
Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Michelle Dubien
Lab Manager