

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: T0175 REPORT No. B14-29373

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 11-Nov-14

DATE REPORTED: 13-Nov-14

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units M.D.L.		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L.			1 MOE E3407	10 SM9215D	
	Reference Method		MOE E3407			
	Date Analyzed/S	Date Analyzed/Site		11-Nov-14/K	11-Nov-14/K	
Client I.D.	Sample I.D.	Date Collected				·
70 Main St. W	B14-29373-1	11-Nov-14	0	0	< 10	

R. Jeco po

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Richard Lecompte
Lab Supervisor