

C.O.C.: T0198

REPORT No. B14-29376

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 11-Nov-14

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 13-Nov-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

<b>Parameter</b>	Total Coliform	E coli	Heterotrophic Plate Count		
<b>Units</b>	cfu/100mL	cfu/100mL	cfu/mL		
<b>M.D.L.</b>	1	1	10		
<b>Reference Method</b>	MOE E3407	MOE E3407	SM9215D		
<b>Date Analyzed/Site</b>	11-Nov-14/K	11-Nov-14/K	11-Nov-14/K		

<b>Client I.D.</b>	<b>Sample I.D.</b>	<b>Date Collected</b>				
#24	B14-29376-1	11-Nov-14	0	0	< 10	



Richard Lecompte  
 Lab Supervisor

M.D.L. = Method Detection Limit  
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill