

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: T0044 REPORT No. B14-31158

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 02-Dec-14

DATE REPORTED: 04-Dec-14
SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

P.O. NUMBER:

WATERWORKS NO. 260019591

	Parameter Units M.D.L. Reference Method Date Analyzed/Site		Total Coliform	E coli		
			cfu/100mL	cfu/100mL		
			1	1		
			MOE E3407	MOE E3407		
			02-Dec-14/K	02-Dec-14/K		
Client I.D.	Sample I.D.	Date Collected				•
#24	B14-31158-1	02-Dec-14	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor