

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW63323 REPORT No. B14-31621

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 08-Dec-14

DATE REPORTED: 10-Dec-14

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units M.D.L. Reference Method Date Analyzed/Site		cfu/100mL 1 MOE E3407	cfu/100mL 1 MOE E3407	cfu/mL 10 SM9215D	
			08-Dec-14/K	08-Dec-14/K	08-Dec-14/K	
Client I.D.	Sample I.D.	Date Collected				·
70 Main St. W	B14-31621-1	08-Dec-14	0	0	< 10	
Pumphouse	B14-31621-2	08-Dec-14	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Natasha Popkie for Richard Lecompte Lab Supervisor