

C.O.C.: DW63438

REPORT No. B14-32756

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 22-Dec-14

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 24-Dec-14

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Parameter	Total Coliform	E coli	Heterotrophic Plate Count		
Units	cfu/100mL	cfu/100mL	cfu/mL		
M.D.L.	1	1	10		
Reference Method	MOE E3407	MOE E3407	SM9215D		
Date Analyzed/Site	22-Dec-14/K	22-Dec-14/K	22-Dec-14/K		

Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr.	B14-32756-1	21-Dec-14	0	0	< 10	



Natasha Popkie
 for Richard Lecompte Lab Supervisor

M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill