

C.O.C.: DW66634

REPORT No. B15-02179

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 02-Feb-15

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 06-Feb-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed	Client I.D.	#24	Pumphouse	Pumphouse
					Sample I.D.			
Total Coliform	cfu/100mL	1	MOE E3407	02-Feb-15/K	B15-02179-1	B15-02179-2	B15-02179-3	
E coli	cfu/100mL	1	MOE E3407	02-Feb-15/K	02-Feb-15	02-Feb-15	02-Feb-15	
Heterotrophic Plate Count	cfu/mL	10	SM9215D	02-Feb-15/K				
Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	03-Feb-15/O		5.0		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		5.0		



M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
 Lab Supervisor