

C.O.C.: DW66638

REPORT No. B15-02180

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 02-Feb-15

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 09-Feb-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

			Client I.D.	#24	Pumphouse	Pumphouse	
			Sample I.D.	B15-02180-1	B15-02180-2	B15-02180-3	
			Date Collected	02-Feb-15	02-Feb-15	02-Feb-15	
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	02-Feb-15/K	0		0
E coli	cfu/100mL	1	MOE E3407	02-Feb-15/K	0		0
Heterotrophic Plate Count	cfu/mL	10	SM9215D	02-Feb-15/K	< 10		
Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1	
Chloroform	µg/L	0.3	EPA 8260	05-Feb-15/O	< 0.3		
Bromodichloromethane	µg/L	0.1	EPA 8260	05-Feb-15/O	< 0.1		
Dibromochloromethane	µg/L	0.1	EPA 8260	05-Feb-15/O	< 0.1		
Bromoform	µg/L	0.1	EPA 8260	05-Feb-15/O	< 0.1		
Total Trihalomethanes	µg/L	0.3	EPA 8260	05-Feb-15/O	< 0.3		



M.D.L. = Method Detection Limit  
 Site Analyzed=K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill

Richard Lecompte  
 Lab Supervisor