

C.O.C.: DW66640

REPORT No. B15-02178

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 02-Feb-15

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 18-Feb-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19 A Buffalo Dr	Pumphouse	Pumphouse	
Sample I.D.	B15-02178-1	B15-02178-2	B15-02178-3	
Date Collected	02-Feb-15	02-Feb-15	02-Feb-15	

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	02-Feb-15/K	0		0	
E coli	cfu/100mL	1	MOE E3407	02-Feb-15/K	0		0	
Heterotrophic Plate Count	cfu/mL	10	SM9215D	02-Feb-15/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	03-Feb-15/O		< 0.1		



M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
 Lab Supervisor