

C.O.C.: DW66703

REPORT No. B15-03318

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 18-Feb-15

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 23-Feb-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19A Buffalo Dr			
Sample I.D.	B15-03318-1			
Date Collected	17-Feb-15			

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	18-Feb-15/K	0			
E coli	cfu/100mL	1	MOE E3407	18-Feb-15/K	0			
Heterotrophic Plate Count	cfu/mL	10	SM9215D	18-Feb-15/K	< 10			
Chloroform	µg/L	0.3	EPA 8260	18-Feb-15/O	6.6			
Bromodichloromethane	µg/L	0.1	EPA 8260	18-Feb-15/O	4.0			
Dibromochloromethane	µg/L	0.1	EPA 8260	18-Feb-15/O	1.9			
Bromoform	µg/L	0.1	EPA 8260	18-Feb-15/O	< 0.1			
Total Trihalomethanes	µg/L	0.3	EPA 8260	18-Feb-15/O	12.6			



M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
 Lab Supervisor