

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW66724 REPORT No. B15-05392

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 17-Mar-15

DATE REPORTED: 19-Mar-15
SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units M.D.L. Reference Method Date Analyzed/Site		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L.			1 MOE E3407	10 SM9215D	
	Reference Meth					
	Date Analyzed/S			17-Mar-15/K	17-Mar-15/K	
Client I.D.	Sample I.D.	Date Collected				•
70 Main St W Lyn	B15-05392-1	17-Mar-15	0	0	80	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Derek Winterton for Richard Lecompte Lab Supervisor