

C.O.C.: DW66683

REPORT No. B15-07300

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 09-Apr-15

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 10-Apr-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

Parameter	Total Coliform	E coli			
Units	cfu/100mL	cfu/100mL			
M.D.L.	1	1			
Reference Method	MOE E3407	MOE E3407			
Date Analyzed/Site	09-Apr-15/K	09-Apr-15/K			

Client I.D.	Sample I.D.	Date Collected				
#24	B15-07300-1	09-Apr-15	0	0		



Derek Winterton
 for Richard Lecompte Lab Supervisor

M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill