

**C.O.C.: G44653**

**REPORT No. B15-09562**

**Report To:**

**Property Management Inc**  
323 Dundas Street East, Unit 3,  
Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
Kingston Ontario K7K 6Z1  
Tel: 613-544-2001  
Fax: 613-544-2770

DATE RECEIVED: 04-May-15

JOB/PROJECT NO.: Lyn Valley Mobile Park


DATE REPORTED: 12-May-15

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

			Client I.D.		Lyn Valley-Effluent	Lyn Valley-Raw		
			Sample I.D.		B15-09562-1	B15-09562-2		
			Date Collected		04-May-15	04-May-15		
Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
E coli	cfu/100mL	1	SM9222B	04-May-15/K	8000	40000		
pH @25°C	pH Units		SM4500H+	08-May-15/K	7.93	7.09		
Total Suspended Solids	mg/L	3	SM2540D	05-May-15/K	8	350		
CBOD5	mg/L	2	SM 5210B	06-May-15/K	4	126		
Phosphorus-Total	mg/L	0.01	E3199A.1	08-May-15/K	1.48	7.44		
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	08-May-15/K	2.0	77.2		
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	11-May-15/K	< 0.01	55.9		
Ammonia (N)-unionized	mg/L	0.01	CALC	11-May-15/K	< 0.01	0.39		
Nitrite (N)	mg/L	0.1	SM4110C	06-May-15/O	1.9	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	06-May-15/O	14.4	0.1		



M.D.L. = Method Detection Limit  
Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte  
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.