

C.O.C.: DW66688

REPORT No. B15-09565

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 04-May-15

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 07-May-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

Client I.D.	#24	Pumphouse	Pumphouse	
Sample I.D.	B15-09565-1	B15-09565-2	B15-09565-3	
Date Collected	04-May-15	04-May-15	04-May-15	

Parameter	Units	M.D.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	04-May-15/K	0	0		
E coli	cfu/100mL	1	MOE E3407	04-May-15/K	0	0		
Nitrite (N)	mg/L	0.1	SM4110C	05-May-15/O			< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	05-May-15/O			3.5	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-May-15/O			3.5	



M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
 Lab Supervisor