

C.O.C.: DW64032

REPORT No. B15-13803

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 10-Jun-15

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 12-Jun-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

| Parameter | Total Coliform | E coli | Heterotrophic Plate Count | | |
|--------------------|----------------|-------------|---------------------------|--|--|
| Units | cfu/100mL | cfu/100mL | cfu/mL | | |
| M.D.L. | 1 | 1 | 10 | | |
| Reference Method | MOE E3407 | MOE E3407 | SM9215D | | |
| Date Analyzed/Site | 10-Jun-15/K | 10-Jun-15/K | 10-Jun-15/K | | |

| Client I.D. | Sample I.D. | Date Collected | Total Coliform | E coli | Heterotrophic Plate Count | | |
|-------------|-------------|----------------|----------------|--------|---------------------------|--|--|
| #24 | B15-13803-1 | 10-Jun-15 | 0 | 0 | < 10 | | |
| Pumphouse | B15-13803-2 | 10-Jun-15 | 5 | 1 | | | |



Derek Winterton
 for Richard Lecompte Lab Supervisor

M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill