

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW64035 REPORT No. B15-13807

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 10-Jun-15

DATE REPORTED: 12-Jun-15

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L. Reference Method Date Analyzed/Site		1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			10-Jun-15/K	10-Jun-15/K	10-Jun-15/K	
Client I.D.	Sample I.D.	Date Collected				·
70 Main St. W.	B15-13807-1	10-Jun-15	0	0	< 10	
Pumphouse	B15-13807-2	10-Jun-15	0	0		

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Derek Winterton for Richard Lecompte Lab Supervisor