

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW66647 REPORT No. B15-15200

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 23-Jun-15

DATE REPORTED: 25-Jun-15

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter Units M.D.L. Reference Method Date Analyzed/Site		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	M.D.L.			1	10	
	Reference Meth			MOE E3407	SM9215D	
	Date Analyzed/S			23-Jun-15/K	23-Jun-15/K	
Client I.D.	Sample I.D.	Date Collected				·
19A Buffalo Dr.	B15-15200-1	23-Jun-15	0	0	< 10	

M.D.L. = Method Detection Limit Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Derek Winterton for Richard Lecompte Lab Supervisor