

C.O.C.: DW69112

REPORT No. B15-19632

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

DATE RECEIVED: 04-Aug-15

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 10-Aug-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed	Client I.D.	#24	Pumphouse	Pumphouse	#24
					Sample I.D.	B15-19632-1	B15-19632-2	B15-19632-3	B15-19632-4
Date Collected					04-Aug-15	04-Aug-15	04-Aug-15	04-Aug-15	04-Aug-15
Total Coliform	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0			
E coli	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0			
Heterotrophic Plate Count	cfu/mL	10	SM9215D	05-Aug-15/K	< 10				
Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O				< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	05-Aug-15/O				< 0.1	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O				< 0.1	
Chloroform	µg/L	0.3	EPA 8260	05-Aug-15/O					< 0.3
Bromodichloromethane	µg/L	0.1	EPA 8260	05-Aug-15/O					< 0.1
Dibromochloromethane	µg/L	0.1	EPA 8260	05-Aug-15/O					< 0.1
Bromoform	µg/L	0.1	EPA 8260	05-Aug-15/O					< 0.1
Total Trihalomethanes	µg/L	0.3	EPA 8260	05-Aug-15/O					< 0.3



R.L. = Reporting Limit  
 Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill  
 Uncertainty Values available upon request

Richard Lecompte  
 Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.