

C.O.C.: DW69113

REPORT No. B15-19633

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 04-Aug-15

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 07-Aug-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

			Client I.D.	#24	Pumphouse	Pumphouse	
			Sample I.D.	B15-19633-1	B15-19633-2	B15-19633-3	
			Date Collected	04-Aug-15	04-Aug-15	04-Aug-15	
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0	
E coli	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0	
Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O			< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	05-Aug-15/O			4.1
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O			4.1



R.L. = Reporting Limit
 Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill
 Uncertainty Values available upon request

Richard Lecompte
 Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.