

C.O.C.: DW69114

REPORT No. B15-19634

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 04-Aug-15

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 10-Aug-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19A Buffalo Dr.	Pumphouse	Pumphouse	19A Buffalo Dr.
Sample I.D.	B15-19634-1	B15-19634-2	B15-19634-3	B15-19634-4
Date Collected	04-Aug-15	04-Aug-15	04-Aug-15	04-Aug-15

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0		
E coli	cfu/100mL	1	MOE E3407	05-Aug-15/K	0	0		
Heterotrophic Plate Count	cfu/mL	10	SM9215D	05-Aug-15/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O			< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	05-Aug-15/O			< 0.1	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	05-Aug-15/O			< 0.1	
Chloroform	µg/L	0.3	EPA 8260	05-Aug-15/O				0.4
Bromodichloromethane	µg/L	0.1	EPA 8260	05-Aug-15/O				< 0.1
Dibromochloromethane	µg/L	0.1	EPA 8260	05-Aug-15/O				< 0.1
Bromoform	µg/L	0.1	EPA 8260	05-Aug-15/O				< 0.1
Total Trihalomethanes	µg/L	0.3	EPA 8260	05-Aug-15/O				0.4



R.L. = Reporting Limit
 Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill
 Uncertainty Values available upon request

Richard Lecompte
 Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.