

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW69213 REPORT No. B15-22777

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 02-Sep-15

DATE REPORTED: 08-Sep-15

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units R.L. Reference Method Date Analyzed/Site		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	R.L.			1 MOE E3407	10 SM9215D	
	Reference Meth					
	Date Analyzed/S			02-Sep-15/K	02-Sep-15/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St. W	B15-22777-1	02-Sep-15	0	0	290	

R.L. = Reporting Llmit

Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill

Uncertainty Values available upon request

Derek Winterton for Richard Lecompte Lab Supervisor