

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

REPORT No. B15-22779 C.O.C.: DW69217

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 02-Sep-15 DATE REPORTED: 08-Sep-15

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter Units R.L. Reference Method Date Analyzed/Site		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	R.L.			1	10	
	Reference Meth			MOE E3407	SM9215D	
	Date Analyzed/S			02-Sep-15/K	02-Sep-15/K	
Client I.D.	Sample I.D.	Date Collected				
19A	B15-22779-1	02-Sep-15	0	0	140	

R.L. = Reporting LImit

Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill

Uncertainty Values available upon request

Derek Winterton for Richard Lecompte Lab Supervisor