

ENVIRONMENTAL LABORATOR ES Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW69118

REPORT No. B15-24099

<u>Report To:</u>	Caduceon Environmental Laboratories				
Property Management Inc	285 Dalton Ave				
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1				
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001				
Attention: Isaac Berman	Fax: 613-544-2770				
DATE RECEIVED: 16-Sep-15	JOB/PROJECT NO.: Lyn Valley Mobile Home				
DATE REPORTED: 18-Sep-15	P.O. NUMBER:				
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465				

	Parameter Units		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
	R.L.		1	1	10	
	Reference Meth	od	MOE E3407	MOE E3407	SM9215D	
	Date Analyzed/Site		16-Sep-15/K	16-Sep-15/K	16-Sep-15/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St. W	B15-24099-1	16-Sep-15	0	0	< 10	
Pumphouse	B15-24099-2	16-Sep-15	0	0		

R.L. = Reporting Llmit Site Analyzed: K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Uncertainty Values available upon request Derek Winterton for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.