

Client committed. Quality assured.

## CERTIFICATE OF ANALYSIS

**Final Report-Microbiology** 

## C.O.C.: DW70285

## REPORT No. B15-25316

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 29-Sep-15	JOB/PROJECT NO.: Lyn Valley Mobile Home			
DATE REPORTED: 02-Oct-15	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465			

	Parameter Units R.L. Reference Method Date Analyzed/Site		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			29-Sep-15/K	29-Sep-15/K	29-Sep-15/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St. W	B15-25316-1	29-Sep-15	0	0	< 10	

R.L. = Reporting Llmit Site Analyzed: K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill Uncertainty Values available upon request Derek Winterton for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.